



April 17, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re: U.S. Patent Application

Patent No. 7,155,824; Issued: January 2, 2007 Application No.: 10/802,673; Filed: March 17, 2004

Title: Method of Manufacturing an Automotive Differential Having an Input Pinion

Inventor: Bryan P. Prucher

Our Reference: 9539-000054/US/CPA

Dear Sir:

We have reviewed the above-identified patent and have found the following errors:

Column 1, Line 14; Application Page 1, Line 9	After "method", insertto a
Column 1, Line 45; Application Page 2, Line 8	After "more", insertthan
Column 3, Line 45; Application Page 6, Line 17	"includes" should beinclude
Column 5, Line 32; Application Page 10, Line 15	"formed" should befrom
Column 7, Line 53; Application Page 15, Line 14	After "manner", insertin
Column 10, Line 39, Claim 20; Application Page 24, Line 2, Claim 20	Delete "that", 2 nd occurrence

Kindly make these errors of record in your files.

Respectfully Submitted

Reg. No. 34,000